

FIG. 1




FIG. 2





FIG. 3



0964881.1 "082800"

003280" FEB 1960

F I G . 4




FIG. 5




FIG. 6




FIG. 7 A




FIG. 7 B




FIG. 7 C






FIG. 7 D




0064001-000000

FIG. 8



0954341.02200

F I G. 1 0



READ DATA
CORRECTION
SECTION

READ DATA
CORRECTION
SECTION

READ DATA
CORRECTION
SECTION

READ DATA
CORRECTION
SECTION

116
(70R, 70G, 70B,
70IR)

116
(70R, 70G, 70B,
70IR)

116
(70R, 70G, 70B,
70IR)

72

78

22

74A

DRIVING
CIRCUIT

DRIVING
CIRCUIT

118

114

112

66

64

FIG. 11




FIG. 12 A





FIG. 12 B



008280 "T. 082800"